



SIERRA WIRELESS END OF LIFE NOTICE

OVERVIEW

| | | | |
|-----------------------------|--|-------------------------|---------------------|
| DATE ISSUED: | June 29, 2012 | TRACKING NUMBER: | EOL-MC879x-06292012 |
| ISSUED BY: | AirPrime Product Management | | |
| PRODUCTS AFFECTED: | MC8790, MC8790V, MC8792V | | |
| SKUs AFFECTED: | ALL SKUs of the MC8790, MC8790V, MC8792V | | |
| URGENCY: | High | | |
| FOR DISTRIBUTION TO: | All customers and their partners | | |

DETAILS

| | |
|--|--|
| EOL DETAILS: | <p>Sierra Wireless hereby announces the EOL of the MC8790, MC8790V and MC8792V PCI Express mini cards. The MC8795V is not affected by this notice.</p> <p>Customers wishing to extend the life of a platform that has integrated the MC8790, MC8790V or MC8792V have two (2) options.</p> <ol style="list-style-type: none">1) Purchase sufficient quantity of the module before the last purchase date to support the projected life of the platform.2) Customers can integrate a newer Sierra PCI Express mini card or other product. <p>For info on Sierra Wireless PCI Express mini cards, and other products, go to: http://www.sierrawireless.com/en/productsandservices/AirPrime/Wireless_Modules.aspx</p> |
| EOL DATES: | <ul style="list-style-type: none">• Last time purchase orders will be accepted until August 31st, 2012• Final shipments must occur prior to December 31st, 2012 |
| FURTHER SUPPORT: | <p>Sierra Wireless will provide ongoing support on a reasonable commercial basis until December 31st, 2013. As previously communicated, regular FW maintenance has ended as of June 29th 2012.</p> |
| FOR FURTHER INFORMATION PLEASE CONTACT: | <p>Your Sierra Wireless sales/technical support contact.</p> |